

SEEK AND FIND

What's Wrong With This Picture?



advance for
Respiratory Care
& Sleep Medicine

ADVANCE

SLEEP STUDY NO-NO'S

SIXTEEN THINGS in this photo violate proper sleep hygiene practices in a patient sleep study room. Are you sharp enough to find all of them? When you're ready to see how you score, [click here](#).

ADVANCE thanks **Brian A. Kraft**, RPSGT, sleep diagnostic and treatment center manager, and staff at University Services, Lansdale, Pa., for creating this scenario. Kraft and **Laura Donovan**, RPSGT, R. EEG T, are seen as techs in this photo. **Sarah Rosenzweig**, RPSGT, ancillary services coordinator, is posing as the patient. And **Casey the dog** appears as himself.

After years of promoting excellent sleep health hygiene and following exacting sleep study procedures, it was a challenge for them to set their professionalism aside to demonstrate incorrect practice.

SEEK AND FIND ANSWERS

How Many Errors Did You Spot?



advance for
Respiratory Care
& Sleep Medicine

1. Laptop on bed
2. Beer bottle
3. Dog on bed
4. CPAP hose on bed frame
5. CPAP mask hanging off
6. Coffee
7. Electrodes taped to patient's head
8. Tech sitting on bed
9. Partially gloved/no gloves
10. Big glob of glue on tech's applicator stick
11. Patient sitting up in bed
12. Head box around tech's neck
13. Big stretch of tape
14. Chest effort belt misplaced over shoulder
15. Tech holding cell phone
16. Messy linens at foot of bed